

THEFT OF LEAD/METALS REGISTER

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED - AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Foremark, St Saviour (Grade I)	5th November 2009	4th lead theft since 2007.	Majority of nave	Temporary Tarpaulin	
Twyford, St Andrew (Grade I)	17th December 2009	unknown	All lead off chancel roof	Stainless steel for upper part of roof with lead sheet cover detail to ridge and hollow rolled lead details to eaves.	Cert. 2644 Faculty granted 12/08/10
Horsley, St Clement (Grade I)	30th March 2010	14th/15th/16th + attempt on 19th March	Removed lead flashing and lead sheeting.	Lead – like-for-like. Authorized by Archdeacon	Archdeacon authorization
Denby, St Mary (Grade I)	28th April 2010 31st August 2010 5th August 2011	Several occasions with eventual removal of all lead + previous theft from extension roof in 2008 29th August End of July beginning of August	Main Roof inc. Nave & North Aisle, South Aisle and New Extension Roof again. Lead flashings Lead flashings from Extension roof	Temporary covering of felt Proposed – stainless steel Temporary work to be done Temporary tarpaulin applied quotation to be given by building contractors.	DAC Cert. 2760 dated 24/05/11 awaiting faculty and funds.
Kirk Langley, St Michael (Grade I)	6th May 2010 7th May 2010 24th July 2010	5th May 2010 6th May 2010 23rd July 2010	Quarter of north aisle Next quarter of north aisle Most of what was left.	Temporary cover of tarpaulin and felt. Proposed – stainless steel	Cert. 2724 dated 15/12/10 Fac. 19/7/11
Breadsall, All Saints (Grade I)	6th May 2010	May 2010	Small area of roof	Replaced with lead	Authorized by Archdeacon.
Middleton-by-Wirksworth, Holy Trinity (Grade II)	7th May 2010	6th May 2010 + 2 previous occasions	Vestry roof	Proposed – Sarnafil	Cert 2678 28/7/10 Faculty granted 14/10/10
					Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED, AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Osmaston, St Martin (Grade II*)	11th May 2010	10th May 2010 + again 15th May 2010	Approx. 30 sq metres taken + 2 lead drainpipes.	Proposed – Sarnafil	Cert 2699
Youlgreave, All Saints (Grade I)	11th May 2010	10th May 2010	Temporary repair done. Lead on porch roof rolled up but not taken – lead from roof ridge removed from sanctuary & copper lightning conductor.	Proposed – unknown Lightning conductor was replaced with aluminium.	
Mappleton, St Mary (Grade II*)	11th May 2010 19th July 2010 10th September 2010	17th July 2010 5th/6th September 2010	Further lead taken – roof Several sheets of lead removed	Temporary covering of felt. Work was being done on roof at the time of the theft. Proposed - Sarnafil or equivalent, still to decide. Temporary tarpaulins used. Temporary tarpaulins used. Application for stainless steel.	DAC cert. 2715 dated 29/11/10 Faculty dated 29/3/2011.
Crich, St Mary (Grade I)	11th May 2010 13th July	10th May 2010 + previous raids in December 2007 and August 2009. 10th June 1 July 8th July 12th July	Approx. 20 sheets removed from both north and south aisles. 2 sheets from south aisle, 2 sheets from north aisle. 6 sheets stolen from Nave 2 sheets stolen from Nave 6 sheets stolen from Nave	Parish propose to replace with stainless steel. Temporary tarpaulin. Parish propose removal of remaining lead making temporary repair and propose replacing with stainless steel.	Cert. 2690 Faculty granted 18/11/2010 Cont/d.....

THEFT OF LEAD/METALS REGISTER Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED - AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Darley Dale, St Helen (Grade II*)	17th May 2010	16th May 2010	Lead removed from nave ridge + small amount and half of south transept + ridge.	Propose to replace with lead.	DAC Cert. 2680 dated 3/8/10
Brailsford, All Saints (Grade I)	May 2010	late May 2010	Thieves broke into church, turned off the alarm system before attempting to steal lead off roof south aisle but didn't succeed. Took lead flashings from boiler house roof	Lead flashings now repaired with flash band.	N/A
Kirk Ireton, Holy Trinity (Grade I)	1st July 2010	29th/30th June 2010	Apex of chancel roof but this lead was recovered from churchyard and peeled back the lead over the chancel and the north aisle roofs but failed to take remove.	Repair the roof and put in an alarm system.	Cert of Alarm system 2685 dated 4/8/10 Faculty dated 23/11/10
Belper, Christ Church (Grade II)	21st July 2010	6th/7th July 2010	Lead from the valley gutter between the northern wall of the church and the pitched roof of the hall and also lead flashing.	Temporary tarpaulin applied. Propose to replace with stainless steel.	
North Wingfield, St Lawrence (Grade I)	8th July 2010	5th/6th July 2010	11 sheets of lead from the side aisle.	To replace with lead. To install alarm system	Cert. 2707 Cont/d.....

THEFT OF LEAD/METALS REGISTER Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED - AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Church Broughton, St Michael (Grade I)	5th August 2010	4th August 2010	Approx. 15 feet of lead removed off the north aisle roof towards the east end.	Temporary plastic sheeting by Derbyshire's of Brailsford and church architect informed. Open to advise on best course of action for repairs.	Alarm system installed DAC Cert. 2713 dated 16/11/10
	13th August 2010	12th August 2010	Attempted theft	Nothing taken – thieves disturbed.	
Pinxton, St Helen (Grade II)	12th August 2010	Recent	Lead flashings from the nave, north aisle, Brookhill aisle and vestry roofs. Estimated 40m length in total	As the roof coverings are interne coated steel they are requesting to use steel for the flashings.	DAC Cert. 2696 dated 20/10/11 Faculty 5/4/2011
Hartington, St Giles (Grade II*)	12th August 2010	8th/10th August	Attempted theft.	Parish wish to remove remaining lead and replace with an alternative material. Temporary tarpaulin applied. Lead was cut up and rolled but the parish has been able to reuse.	Alarm system installed Cert. 2709 dated 15/11/10 Faculty 27/3/11.
	20th August 2010	12th August	Theft of lead from the north aisle.		
Whitwell, St Lawrence (Grade I)	1st September 2010	31st August 2010	Removed 8/9 sheets of lead from west slope of north transept roof.	Temporary tarpaulin applied. Intend replacing with Stainless Steel.	Cert. 2701 dated 28/10/10 Faculty 14/4/11 Cont/d.....

THEFT OF LEAD/METALS REGISTER Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED - AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Wirksworth, St Mary (Grade I)	8th September 2010	Not known – possibly 7th September 2010.	One panel of lead removed two damaged from roof area over the choir and clergy vestries, which lie parallel to the south transept and are approached off the transept.	Temporary covering to replace with lead.	
Old Brampton, St Peter and St Paul (Grade I)	6th August 2010	Unknown	North aisle – approx. 11 sheets were removed and not taken away.	As contractors were on site these were replaced the next day.	Alarm System installed cert. 2752/A 3/11/11
South Wingfield, All Saints (Grade II*)	21st February 2011	18th February 2011	Theft of 7 metre strip of guttering lining.	Proposing to replace with soft zinc.	
Kirk Ireton, Holy Trinity (Grade I)	7th April 2011	Unknown	Lead stolen approx. £2,000 in value		
Allenton, St Edmund (Unlisted)	27th February 2011	Unknown	Lead stolen between the tower and the main roof	Quotation obtained for £4,500 which includes internal redecoration to make good where the water came in.	DAC Cert. 2780 dated 2/8/11
Allenton, St Edmund (Unlisted)	24th March 2011	Unknown	Attempt to take the flashings on the porches.		
Dinting Vale, Holy Trinity (Grade II)	12th June 2011	8th and 9th June	Small amount of lead flashings damaging roof tiles in the process	Considering the use of Ubiflex.	Cont/d....

THEFT OF LEAD/METALS REGISTER Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED - AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Eckington, St Peter & St Paul (Unlisted)	6th July 2011	Within previous 2 weeks.	Small amount but over the organ area causing £40k worth of damage	Plastic tarpaulin and intend to do a repair during week commencing 11th July 2011.	DAC Cert. 2794 dated 15/09/11 Cert 2802 alarm s.
Hathersage, St Michael & All Angels (Grade I)	18th July 2011	Between 13th – 17th July 2011	North aisle roof	Covering with tarpaulin. Temporary use of felt. May decide to completely re-roof with stainless steel. The parish intend to replace the north aisle roof with stainless steel.	DAC Cert. 2795 dated 5/10/11.
Edale, Holy & Undivided Trinity (Grade II)	19th July 2011	17th or 18th July 2011	Church tower area affected – small piece of lead taken but larger amount bent over.	Temporary measure was to call in roofing specialist who is to inspect the roof (19/7/11) repair some dislodged tiles, ensure the bent lead which was put back into its normal shape is not cracked and undertake any other immediate repairs.	
Fairfield, St Peter (Grade II)	16th August 2011	14th/15th August 2011	Apex of main body of church. Having removed 5ft x 2ft piece of lead the thieves did not remove the lead as they may have been disturbed, it was left at the side of the church.	The lead was successfully put back onto the church and re-marked with Smartwater. PCC considering security lights after advice from Police.	N/A
Stapenhill, St Peter (Grade II)	11th August 2011	7th August 2011	Vestry roof	To use an alternative material possibly, stainless steel	DAC 2807 27/10/11

THEFT OF LEAD/METALS REGISTER Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED - AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Chapel-en-le-Frith (Grade II*)	16th August 2011	15th August 2011	Lead round 3 sides of Becket Room Roof and the flashings on the 3 high-level Becket Room windows. The Becket Room being built onto the north wall of the Church	No temporary measures were required as the parish repaired the damage with Ubilflex as an alternative to any metal.	N/A
Castleton, St Edmund (Grade II*)	24th August 2011	Some time ago	Half the Lead taken from church porch	Lead has been replaced paid for by the insurance	
Stapenhill, St Peter (Grade II)	30th August 2011	During W/Comm. 22nd August 2011	Attempt on the south aisle roof.	Lead not removed, peeled back.	N/A
Osmaston, St Martin (Grade II*)	5th September 2011	3rd September 2011 (Saturday)	Theft of lead downpipes (4)	Wanting to replace with an alternative material but the parish haven't decided on what material yet. Reported to Police 4th or 5th Sept. 2011.	DAC Cert. 2699 dated 3/3/2011.
Stoney Middleton, St Martin (Grade II*)	5th September 2011	During W/Comm. 22nd August 2011	Theft of Silver Parish to replace all items.	3 Chalices, 1 Flagon, 2 Pattens, 1 tankard, 1 small pyx, 1 baptismal shell	Value for insurance £100,000
Curbar, All Saints (Unlisted)	5th September 2011	Approx. beginning of August 2011	Lightning Conductor strip taken - (not copper)	25 yards of lightning conductor stolen from the length of the north aisle.	
Etwall, St Helen (Grade I)	7th September 2011	Attempt to take lead	Lead above North-west part of the parapet was peeled back	N/A	N/A

THEFT OF LEAD/METALS REGISTER Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Doveridge, St Cuthbert (Grade I)	Letter received from parish dated 15 September 2011	Not known	Two thefts reported 1. Lead flashing worth approx. £50 caused £1,000 damage. 2. Half the north aisle was stripped.	Discussing the possibility of replacing with zinc or stainless steel with church architect.	
Hope, St Peter (Grade I)	14th September 2011	Silver Theft between Thursday 21st July and Sunday 24th July 2011.	<u>Silver:</u> Flagon 1715 Communion cup and cover (chalice and patten) 1662 Plate 1665 (given in 1711) Chalice and patten 1977/1976 (Queens Jubilee) Sheffield Pair of vases 1919 Sheffield Pair of vases 1901 Sheffield Pair of candlesticks 1898 Sheffield Longshaw cup 1924 Sheffield Pyx 1957 Communion set 1964 in travelling case (we still have one glass flask in the Aumbrey) Viaticum 1961 <u>Electro-plate:</u> One jug (we retain the other of the pair) 1991 Pair of jugs on plate 1972 - No photo available	Approx. £100,000 figure given to Police and insurance. The Parish do not intend to replace the items but to purchase something very special and new with any money received from the insurance.	
Staveley, St John (Grade B)	Lead Theft			To replace with lead approx. £2,000 in value.	
Osmaston, St Martin (Grade II*)	2 Thefts of Lead	Sent email 19/9/11	for details to Paul Taylor		

THEFT OF LEAD/METALS REGISTER Cont/d.....

CHURCH	DATE THEFT REPORTED TO DAC	DATE THEFT OCCURRED (If known)	AREA(S) OF ROOF AFFECTED AND/OR ITEMS TAKEN	REPLACEMENT MATERIALS USED	DAC CERT. NO./ FACULTY DATE
Chelmorton, St John the Baptist (Grade II*)	20 September 2011	14th September 2011	Lead sheeting removed from over chancel and SE transept roof + flashings.	Plastic sheeting has been applied as a temporary covering, awaiting roofers to put on a better temporary covering. The parish have made no decision yet as to its replacement.	DAC Cert. 2806 dated 27/10/11
Mugginton, All Saints (Grade I)	20 September 2011	16th September 2011	Lead taken from whole of the ridge of the roof and an area of lead was torn up but not taken from over the nave at the tower end on the north side.	Temporary covering of plastic sheeting to ridge of roof and the torn lead was put back into position by Linfords of Lichfield. The parish are wanting to apply security to the roof	Alarm system DAC cert. 2815 dated 7/11/11
Taddington, St Michael (Grade I)	26th September 2011	25th September 2011	Lead sheets taken from north aisle roof above the organ.	Temporary tarpaulin both externally and internally to protect the organ.	DAC Cert. 2804 dated 26/10/11
Youlgreave, All Saints (Grade I)	29th September 2011	28th September 2011	Eight panels of lead removed.	A J Restoration to be contacted as they did the work after the last theft in Spring. The parish are loathed to replace with lead and are considering an alternative material.	
Kirk Ireton, Holy Trinity (Grade I)	27 October 2011	N/A	Attempted lead theft no damage done.	Alarm was activated which appears to have deterred theft.	N/A
Wirksworth, St Mary (Grade I)	18 November 2011	16th November 2011 Possibly zinc	Piece of metal grave furniture from graveyard	Upright decorative poly supports railing around grave	N/A